

Milling machine quick start guide

Turn on main breakers

Turn on servo amp breakers

BIG FAN will blow like crazy

Capacitors are at about 180V (amplifiers max 200V)

MAKE sure pot on control box is centered.

Connect the control box to one of the axis.

Turn on that axis on the servo amplifier box

Turn pot with caution